

DERAILMENT
HAPPENED
HERE

ADD POWER
FEED HERE?

SWITCH THAT
SEEMS TO BE
CAUSING THE
PROBLEM

NO POWER

