


SERVICE MANUAL

OTEP 95



Broken tab on coil bracket may be repaired by using 6-32 x 1" round head screw, as shown. On illustrated bracket be sure to keep screw hole close to the corner of the bracket to avoid interference with the bakelite coil form.