

Originally Posted by lionelsoni:

Do you have a "true RMS" voltmeter? Most AC voltmeters assume that you are measuring a sinusoidal waveform, which the CW-80 definitely does not put out. Here is a correction chart for use with an ordinary voltmeter:

Meter	RMS
0	0
0.5	1.6
1	2.7
1.5	3.7
2	4.6
2.5	5.4
3	6.1
3.5	6.9
4	7.5
4.5	8.2
5	8.8
5.5	9.5
6	10
6.5	10.6
7	11.2
7.5	11.7
8	12.2
8.5	12.7
9	13.2
9.5	13.7
10	14.1
10.5	14.6
11	15
11.5	15.4
12	15.8
12.5	16.2
13	16.6
13.5	16.9
14	17.3
14.5	17.6
15	17.9
15.5	18.2
16	18.5
16.5	18.8
17	19
17.5	19.3
18	19.5
18.5	19.7
19	19.8
19.5	19.9
20	20