



Sequence is done, turn off soft alarm and reset sequence bits for next cycle.

0045



Manual mode program is skipped, de-energize all track

0046



0047

&lt;END&gt;

THIRD -B

LAD 3 - USER\_FAULT --- Total Rungs in File = 1

0000

END

THIRD -B

LAD 4 - HSC\_INT --- Total Rungs in File = 1

0000


END

THIRD -B

LAD 5 - STI\_INT --- Total Rungs in File = 1

0000

END





LAD 6 - THROW SW --- Total Rungs in File = 18

