


LIONEL SERVICE MANUAL

OTIP 35



The components of the Motor Assembly 2055-100 are, including parts of the collector assembly are illustrated on Page 4, Section LOC-2035.

Additional components of the Smoke Generator are listed on Page 4, Section LOC-SU.