

SERVICE MANUAL

OTIP:95

TYPE "KW" TRANSFORMER REVISION

Type "KW" transformers manufactured since 1957 were made with riveted lamination stacks which required a change in the dimensions of the coils and of the coil brackets.

Replacement of the older coils with new coils requires the use of new brackets as well. The new components and their assembly are illustrated below.

