

SERVICE MANUAL

MILK CAR NO. 3472 (1950 MODEL)

No. 3472 Milk Car produced in 1950 and thereafter differs from earlier models principally in the following respects: The metal swinging doors replaced by plastic doors and door frames. The roof door enlarged and rehung for easier opening. The mechanism redesigned for better assembly and operation and the car frame changed to accommodate the new doors.

In order to remove the car body from the frame, the frame springs must first be taken out in the usual fashion and the plastic door frames snapped out by pulling outward from the bottom. When replacing doors be careful to examine them for burrs along the edges and also on the inner surface where they might interfere with the door-opening part of the mechanism.

